

MAJOR REPAIR AND ALTERATION (Airframe, Powerplant, Propeller, or Appliance)

Form Approved OMB No. 2120-0020

For FAA Use Only

Office Identification

AEA-FSPU-07

INSTRUCTIONS: Print or type all entries. See FAR 43.9, FAR 43 Appendix B, and AC 43.9-1 (or subsequent revision thereof) for instructions and disposition of this form. This report is required by law (49 U.S.C. 1421). Failure to report can result in a civil penalty not to exceed \$1,000 for each such violation (Section 901 Federal Aviation Act of 1958).

PIPER rial No. 24-4297 Ime (As shown on registration				-2 4 -260 ad Registration M	lark		
rial No. 24-4297 Ime (As shown on registratio		. <u> </u>			lark		
24-4297 ame (As shown on registratio	n contribute		Nationality ar	d Registration M	lark		
ime (As shown on registratio	n contributo			Nationality and Registration Mark			
	o costilicate	N8842P					
CHAVED GEODGE	ii cei iiiicale	te) Address (As shown on registra			ation certificate)		
2. Owner SHAVER GEORGE D GAUSS ROGER W			2105 BELLVALE RD FALLSTON MD 2104				
*The dat		3. For FAA Use					
airworth aircraft, In FAR 4 0 9-24	iness requisions subject to	conformity inspersed 43.7.	ection by a pers	e above descri	e bed		
		4. Underdentido	of FAA inspect	Or	5. Type		
Make		Model		Serial No.	Repair	Alteration	
AIRFRAME (As described in Item 1 above)					XX		
						†	
pe							
nufacturer							
	6	. Conformity Sta	tement		<u> </u>		
and Address		B. Kind of Ager	ncy	c	Certificate No.		
MICHAEL R STURGES 2425 CRESWELL RD BEL AIR MD 21015		VX U.S. Certificated Mechanic Foreign Certificated Mechanic			315681081		
		Certificated Repair Station			7		
		Manufacture	<u> </u>				
ade in accordance with the re	guirements	of Part 43 of the	tem 4 above and c U.S. Federal Avia	lescribed on the r tion Regulations	everse or attachme and that the infor	nts hereto nation	
		Signature of Au	thorized Individu	1 /			
2001		MICHAEL R	STURGES	5	<u>~.</u>		
authority given persons spe the Federal Aviation Adminis	cified below stration and	v, the unit identifies XD APPROV	ied in item 4 wa: /ED	s in <mark>spected</mark> in th	e manner prescrit	ed by the	
Manufactures	XX	Inspection Author	rization	ther (Specify)			
	,	Person Approved Canada Airworthi	by Transport ness Group	_			
Designation				27	7		
2001 31568108	1 [MICHAEL R S	STURGES	\sim			
	Make Make	Make Make	Date Signature 4. Unadiantition Make Model A. Unadiantition 4. Unadiantition Make Model A. Unadiantition A. Unadiantition Model A. Unadiantition A. Unadiantition Model A. Unadiantition A. Unadiantition A. Unadiantition Model A. Unadiantition A.	TAS Date In FAR 43, Section 43.7.	pe and Address B. Kind of Agency A. U.S. Certificated Mechanic Foreign Certificated Repair Station B. Certificated Repair Station Certificated Repair Station Controlly Repeated In the U.S. Federal Aviation Regulations rein is true and correct to the best of my knowledge 2001 Marufacturer 6. Conformity Statement 8. Kind of Agency C. R. STURGES SWELL RD Foreign Certificated Mechanic Certificated Repair Station Manufacturer Above and described on the U.S. Federal Aviation Regulations rein is true and correct to the best of my knowledge 2001 MICHAFL R STURGES 7. Approval for Return To Service authority given persons specified below, the unit identified in item 4 was inspected in the Federal Aviation Administration and is Capperoved by Transport Canada Airworthiness Group Repection Certificate or Designation No. Signature of Authorized Individual	A. Unastartition of An Inspector 4. Unastartition of An Inspector 4. Unastartition of An Inspector 5. Type Make	

NOTICE

Weight and balance or operating limitation changes shall be entered in the appropriate aircraft record. An alteration must be compatible with all previous alterations to assure continued conformity with the applicable airworthiness requirements.

8. Description of Work Accomplished

(If more space is required, attach additional sheets, Identify with aircraft nationality and registration mark and date work completed.)

N8842P

BASIS FOR APPROVAL: PREVIUOSLY APPROVED FORM 337 DATED 8-31-98

(ATTACHED) AND PIPER PA24 SERVICE MANUAL SECTION

IV, PARA 4-47 STRUCTURAL REPAIRS.

DISCRIPTION OF WORK PERFORMED: REPAIR TO REINFORCE CRACKED STRINGERS

PART NUMBERS 23743-04 LEFI AND 23743-05 RIGHT, BETWEEN

BULKHEAD FUSELAGE STATIONS 66.0 AND 70.0.

THE TWO, TOP AND BOTTOM REINFORCEMENTS ARE MADE FROM ALCLAD .040 T3 2024 ALUMINUM. FORMING REINFORCEMENTS WERE DONE PER AC 43 13-1A CHAPTER 4, FIG. 4-17 PARA 4-58 K THRU I. AND PARA 4-59 A & B REPAIR OF CRACKED MEMBER. REINFORCEMENTS WERE TREATED WITH ZINK CHROMATE BEFORE ASSEMBLY. RIVITING WAS PERFORMED PER AC 43 13 1A CHAPTER 4, PARA 4-57 B,C,&E. RIVIT SPACING

USED MANUFACTURES EXISTING PATTERN.


WEIGHT AND BALANCE: NEGLIGIBLE

DATE WORK PERFORMED: 10 SEPT 2001

-----END------END-----

NOTICE

Weight and balance or operating limitation changes shall be entered in the appropriate aircraft record. An alteration must be compatible with all previous alterations to assure continued conformity with the applicable airworthiness requirements.



NOTICE

Weight and balance or operating limitation changes shall be entered in the appropriate aircraft accord. An alteration must be compatible with all previous afterations to assure continued conformity with the applicable aircraft accord. An alteration must be

B. Description of Work Accomplished (If more space is required, attach additional sheets. Identify with sircraft nationality and registration mark and date work completed.)

This repair was done to reinforce cracked stringers part numbers 23743-04 left and 23743-05 right, between bulkhead fuselage stations 66.0 and 70.0. The two, top and bottom, reinforcements(see diagram 2 below) are made from Alclad .040 2024 T3 Aluminum. Forming reinforcements was done as per A.C.43.18-1A Chg 3, Chapter 2, Section 3, pars. 97.a. The design of the repair was done as per A.C.43.13-1A Chg 3, Chapter 2, Figure 2.25; Pars. 100 for working with a stringer; and Paragraph 101 for repairing a cracked member. Treated reinforcements with zinc chromate before assembly. All riveting was done as per A.C.43.13-1A Chg3, Chapter 2, Section 3, Pars. 99. All hardware selection was done as per A.C.43.13-1A Chg.3, Chapter 5, Section 1. All rivet spacing was done as per manufacturer spacing in that area. (See Diagram 1- area before repair was done). Diagram 3 is the repair with reinforements installed. All work done in accordance with Piper PA24 Service Manual, Section IV, pars.4-47, Structural Lepatrs. Weight and Balance

