





Service Letter No. 310

November 10, 1958

TO: All Distributors, Dealers, Owners and Operators

SUBJECT: Locking of Landing Gear Motor Release Arm

MODELS AFFECTED: PA-24 and PA-24 "250" Serial Numbers 24-1 to 24-504 inclusive

The safety wire used to hold the landing gear retraction motor release arm in a closed position shall be replaced on the above mentioned airplanes by an elastic strap, part number 21836-00, per sketch on the reverse side of this letter.

This elastic strap can be obtained from your nearest Piper distributor free of charge until June 1, 1959. To secure this material free of charge it will be necessary that the aircraft serial number or numbers be included on all purchase orders.

No warranty labor will be allowed.

Very truly yours,

AIRCRAFT CORPORATION PIPER


allono 100

Rolland Boardman Service Manager

RB:mm

PIPER AIRCRAFT CORPORATION, LOCK HAVEN, PA., U. S. A.

LOCK HAVEN, PENNSYLY NIA	PIPER AIRCRAFT CORPORATION	SERVICE LETTER NUMBER 310	GEAR MOTOR RELEASE HANDLE STRAP INSTALLATION
A .	NC	10	T









Service Letter No. 311

November 22, 1958

TO: All Distributors, Dealers and Owners

SUBJECT: PA-24 1959 Owners Handbook

It has been noted that on Page 24 of the subject handbook, Item 6 states: "Attach safety lock to handle."

In view of the fact that there is no such piece of equipment on the aircraft, Item 6 should be deleted.

Very truly yours,

PIPER AIRCRAFT CORPORATION

Vov 00

Rolland Boardman Service Manager

RB:mm