

SERVICE



LETTER

Service Letter No. 346

September 29, 1960

TO: Distributors, Dealers, Certified Service Centers and Owners

SUBJECT: Relocation of Safety Belt Buckle - Right Front Seat Only

MODELS AFFECTED: PA-24 Comanches - Serial Nos. 24-1252 (Start of Reclining Seats) to 24-2243 inclusive.

We have been advised that there is a possibility of the buckle on the safety belt on the right front seat becoming lodged under the landing gear handle.

To avoid this possibility, it is recommended that the safety belt be removed and reinstalled in reverse. The buckle end will then be on the door side of the seat.

Very truly yours,

PIPER AIRCRAFT CORPORATION


Wes Holmes
Service Manager

WH:pez

PIPER AIRCRAFT CORPORATION, LOCK HAVEN, PA., U. S. A.