

# SERVICE



# LETTER

Service Letter No. 434

September 30, 1964

TO: Distributors, Dealers, Certified Service Centers and Owners

SUBJECT: Lycoming Service Instruction No. 1110  
(Improved Replacement AC Fuel Pump)

MODELS AFFECTED: PA-24 "250" Comanches (Lycoming Model O-540 series carburetor engines only)

When replacing the engine driven fuel pump, per Lycoming Service Instruction No. 1110, on the PA-24 "250" Comanche aircraft, it will be necessary to discard the original fuel pump baffle and replace with fuel pump baffle, part number 25006-00.

**PIPER AIRCRAFT CORPORATION, LOCK HAVEN, PA., U. S. A.**