

SERVICE



LETTER

Service Letter No. 446

March 1, 1965

TO: Distributors, Dealers, Certified Service Centers and Owners

SUBJECT: Fuel Leakage at the Fuel Cell Gauge

MODELS AFFECTED: PA-24-400 Serial Nos. 26-3 to 26-15 incl., 26-17, 26-18, 26-21 to 26-33 incl., 26-35 to 26-39 incl., 26-41 to 26-46 incl., 26-48 to 26-53 incl., 26-55 to 26-61 incl., 26-63 to 26-69 incl., 26-72 to 26-74 incl., 26-76 to 26-79 incl., 26-81 to 26-90 incl., 26-92 to 26-95 incl., 26-98, 26-106, 26-109, 26-116

COMPLIANCE DATE: Prior to but not later than next 25 hours of operation

Reports indicate that fuel leaks have developed around the inboard fuel gauge mounting screws in the outboard fuel cells of the PA-24-400

A Kit 756 902 has been developed to eliminate this condition.

Each kit contains sufficient material to accomplish this rework on one complete airplane or two (2) fuel cells.

Credit will be allowed for the Kit 756 902 and two (2) hours of warranty labor on receipt of a Warranty & Credit Claim.

