

SERVICE



LETTER

Service Letter No. 465

December 20, 1965

TO: Distributors, Dealers, Certified Service Centers
and Owners

SUBJECT: Airworthiness Directive No. 65-25-3

MODELS AFFECTED: PA-24 and PA-24-250 Comanches, Serial Nos. 24-1
to 24-922 incl., 24-924 to 24-3225 incl.

Orders received as a result of the subject airworthiness directive clearly indicate that a misunderstanding exists insofar as material required for compliance.

An abnormal amount of orders have been received for the Drag Link Assembly, part number 754 429, since issuance of the subject airworthiness directive. This drag link assembly is definitely not required for compliance therewith and although it does include all the required material it should only be secured on a normal replacement parts basis when replacement of the drag link itself is required.

Information concerning material required for this directive is contained in the following Piper service releases:

Service Letter Number 366 Dated January 3, 1962
Service Letter Number 445 Dated April 21, 1965

PIPER AIRCRAFT CORPORATION, LOCK HAVEN, PA., U. S. A.