

SERVICE No. 542 LETTER

Piper Aircraft Corporation

Lock Haven, Pennsylvania, U.S.A.

February 17, 1970

Subject:

Models Affected:

Serial Numbers Affected:

Compliance Time:

Purpose:

Instructions:

Control Surface Travel and Cable Tension

PA-30 Twin Comanche

30-1 to 30-1956 incl., 30-1958 to 30-1976 incl., 30-1978 to 30-1984 incl., 30-1986.

Recommended at the next 100 hour inspection.

To provide service manual instructions for control surface travels and cable tensions for the model PA-30.

Contained in new issue PA-30 Service Manual, Part No. 753 645, Complete Revision No. CR 690625, as follows:

1. Section V

- a. Table V-I, page 5-2
- b. Paragraphs 5-29 to 5-47 incl., pages 5-29 to 5-42 incl.
- c. Figures 5-8, page 5-30; fig. 5-9, page 5-31; fig. 5-10, page 5-33, fig. 5-11, page 5-35; and figs. 5-12 and 5-13, page 5-36.

2. Section VII

- a. Paragraphs 7-13 to 7-15 incl., pages 7-12 to 7-14 incl.
- b. Figures 7-3 and 7-4, page 7-12; figs. 7-5 and 7-6, page 7-13; and fig. 7-7, page 7-14.

The above specified service manual data is attached to this letter, and appears in the same context as contained in the new issue PA-30 Service Manual Part No. 753 645, Complete Revision No. CR 690625.

Perform steps 1 through 7, as follows:

Step	*Page No.	* Paragraph No.	
1.	5-35	5-37, a thru b.1	
2.	5-35	5-37, c.thru c.3	
3.	5 - 35	5-37 , b .2 thru 8	

(over)

Disposition of Replaced Parts:

Instructions: (Continued)	Step *Page No. 4. 5-14 & 5-42 5. 5-2 6. 5-36 7. 5-36	*Paragraph No. 5-45, a. thru k. Table V-I 5-37, c.6 5-37, c.7 thru d.
	*Reference new PA-30 Servic Complete Revision No. CR 6	
Material Required:		No. 753 645 Complete Revision noted in Instructions, above;
Availability of Parts:	Not applicable.	
Material Allowance:	Not applicable.	
Labor Allowance:	Not applicable.	
Material/Labor Allowance Termination Date:	Not applicable.	
Disposition of Parts in Stock:	Not applicable.	

Not applicable.