

# SERVICE



# LETTER

Service Letter No. 302

August 19, 1958

TO: All Distributors, Dealers, Owners and Operators

SUBJECT: Fuel Gauge Ground Wire

MODELS AFFECTED: PA-24 and PA-24 "250" Airplanes  
Serials 24-1 to 24-241 inclusive

To insure a more positive operation of the fuel gauges on the above mentioned airplanes, it is recommended that a ground wire be installed at the rear of the instrument cluster in accordance with the sketch on the reverse side of this letter.

Very truly yours,

PIPER AIRCRAFT CORPORATION

A handwritten signature in dark ink, appearing to read "R Boardman", written in a cursive style.

Rolland Boardman  
Service Manager

RB:mm

PIPER AIRCRAFT CORPORATION, LOCK HAVEN, PA., U. S. A.

FUEL GAUGE GROUND WIRE	
SERVICE LETTER	NUMBER 302
PIPER AIRCRAFT CORPORATION	
LOCK HAVEN, PENNSYLVANIA	

