

SERVICE



LETTER

Service Letter No. 418

December 16, 1963

TO: Distributors, Dealers, Certified Service Centers and Owners

SUBJECT: Replacement of Fuel Flow Gauge

MODELS AFFECTED: PA-30 Twin Comanches, Serial Numbers 30-1 to 30-195 incl.
30-197 to 30-204 incl.

A new fuel flow gauge, part number 24536-00, is now available to replace fuel flow gauge, part number 23861-00, now installed in the aircraft indicated by the above serial numbers.

The original fuel flow gauge, part number 23861-00, has not always registered accurately and the new gauge should be installed promptly.

The new fuel flow gauge, part number 24536-00, will be provided by automatic factory distribution. It will not be necessary for you to submit your purchase orders for your requirements.

Credit will be issued for the new gauge and one (1) hour of warranty labor upon receipt of a warranty and credit claim form and the old fuel flow gauge.

Very truly yours,

PIPER AIRCRAFT CORPORATION

WH:jf


Wes Holmes
Service Manager

PIPER AIRCRAFT CORPORATION, LOCK HAVEN, PA., U. S. A.