

# SERVICE



# LETTER

Service Letter No. 437

November 4, 1964

TO: Distributors, Dealers, Certified Service Centers and Owners

SUBJECT: Replacement of Fuel Gage Assembly

MODELS AFFECTED: PA-24-400 Comanches, Serial Numbers 26-2 to 26-60 incl., 26-65 to 26-69 incl., 26-71 to 26-79 incl., 26-82, 26-84 to 26-87 incl., 26-89, 26-90, 26-92 to 26-96 incl., 26-114, 26-123, 26-124

COMPLIANCE DATE: Within next 100 hours of operation

Reports of corroded inboard fuel gage assemblies in the outboard fuel cell makes it necessary to replace this unit. See sketch on the reverse side of this letter for proper location of fuel gage assembly.

Replacement fuel gage assemblies should be ordered under part number 450 771 (2 per airplane).

Credit will be issued for the gage assemblies and one (1) hour of warranty labor upon receipt of a Warranty and Credit Claim.

(Over)

**PIPER AIRCRAFT CORPORATION, LOCK HAVEN, PA., U. S. A.**

# SERVICE LETTER

## No. 437

