



SERVICE LETTER

No. 549

Piper Aircraft Corporation

Lock Haven, Pennsylvania, U.S.A.

March 20, 1970

Subject: New Owner's Handbooks

Models Affected: PA-30 Twin Comanche "C"

Serial Numbers Affected: 30-1717, 30-1745 to 30-2000 incl.

Compliance Time: Immediate

Purpose: To provide new PA-30 Twin Comanche "C" or Turbo Twin Comanche "C" Owner's Handbooks (reference Material Required, below).

CAUTION: All copies of PA-30 Twin Comanche "C" Owner's Handbooks, part number 753 773, dated prior to January 1970 and PA-30 Turbo Twin Comanche "C" Owner's Handbooks, part number 753 778, dated prior to March 1970 must be destroyed.

Material Required: One (1) each part number 753 773 Owner's Handbook (normally aspirated) January 1970 issue or
One (1) each part number 753 778 Owner's Handbook (turbo-charged) March 1970 issue.

Availability of Parts: Piper Dealer (see NOTE below).

Material/Labor Allowance: Not applicable.

Disposition of Replaced Parts and
Disposition of Parts in Stock: All copies of the PA-30 Twin Comanche "C" Owner's Handbook dated prior to January 1970 (753 773) or March 1970 (753 778) must be destroyed.

NOTE

A copy of the appropriate new PA-30 Twin Comanche "C" Owner's Handbook is being mailed direct to all PA-30 Twin Comanche "C" owners of record on a no charge basis.

SUBJECT: New Owners Handbooks

The following is a summary of the new owners handbooks previously released and supplied to all owners. This summary is for reference purposes only.

<u>Aircraft Ser. No. Identification</u>	<u>Owner Handbook Identification</u>	<u>Type Service Release</u>	<u>Date Service Release</u>	<u>Distribution Schedule</u>
(1) PA-30 "C" Non-Turbo; Ser. Nos. 30-1717, 30-1745 to 30-2000 incl.	753 773; issue Jan. 1970	Service Letter No. 549	3/20/70	Distributors and Owners
(2) PA-30 "C" Turbo Ser. Nos. 30-1717 30-1745 to 30-2000 incl.	753 778; issue March 1970	Service Letter No. 549	3/20/70	Distributors and Owners
(3) PA-30 "B" Non-Turbo; Ser. Nos. J-853, 30-902 30-1716 incl., 1718 to 30-1744 incl.	753 697; issue March 1970	Piper Letter (unnumbered) dated 4/16/70	4/16/70	Distributors and Owners
PA-30 "B" Turbo Ser. Nos. 30-853, 30-902 to 30-1716 incl., 30-1718 to 30-1744 incl.	761 452; issue May 1970	Piper Letter (unnumbered) dated 5/5/70	5/5/70	Distributors and Owners
(5) PA-30 Ser. Nos. 30-1 to 30-852 incl., 30-854 to 30-902 incl.	753 644; issue May 1970	Piper Letter (unnumbered) dated 5/12/70	5/12/70	Distributors and Owners

SPECIAL NOTE: to Piper Distributors and Piper Dealers

Reference the computer listing of PA-30 owners supplied with advance copies of Service Letter No. 552 to determine the extent of the factory owner mailing of PA-30 Owner's Handbooks in your area. Cautionary reminder: Be sure all owners of aircraft not appearing on this list receive the appropriate new owner handbook.

This addendum is to be attached to and become a permanent part of Service Letter No. 549