

The logo consists of the word "PIPER" in a bold, sans-serif font, enclosed within a dark, rounded rectangular border.

Customer Services

SERVICE LETTER

No. 610

Piper Aircraft Corporation

Lock Haven, Pennsylvania, U.S.A.

February 28, 1972

Subject: PA-24 Comanche Service Manual Temporary Revision TR720127; Tail Control Surface Inspection, Maintenance and Repair Information

Models Affected: PA-24 Comanche Series

Serial Numbers Affected: PA-24-180, PA-24-250 and PA-24-260; 24-1 and up. PA-24-400; 26-1 and up.

Compliance Time: The subject Temporary Revision should be provided to all registered PA-24 Service Manual owners as soon as possible.

Purpose: To update the PA-24 Service Manual, Piper part number 753 516 to include the tail control surfaces inspection, maintenance and repair guidelines set forth in the Temporary Revision dated January 27, 1972 (TR720127), and to provide distribution thereof.

The information contained in Temporary Revision TR720127 will be incorporated in a Permanent Revision in the future; use of the Temporary Revision procedure enables advance release of this information.

Instructions: Contained in Temporary Revision TR720127.

Material Required: One (1) each Temporary Revision TR720127 to PA-24 Service Manual Piper Part Number 753 516.

Availability of Parts: General distribution copies of TR720127 are available through Piper Dealers.
