

SERVICE



LETTER

Service Letter No. 451

May 14, 1965

TO: Distributors, Dealers, Certified Service Centers and Owners

SUBJECT: Fuel System Purging Valve

MODELS AFFECTED: PA-24-400, Serial Nos. 26-6 to 26-15 incl., 26-17 to 26-19 incl., 26-21 to 26-79 incl., 26-82 to 26-96 incl., 26-98, 26-99, 26-101 to 26-103 incl., 26-105, 26-106, 26-108, 26-109, 26-111 to 26-117 incl., 26-121 to 26-124 incl., 26-135, 26-140, 26-147.

COMPLIANCE DATE: Prior to but not later than next 50 hours of operation

Under high temperature conditions it is possible to develop vapor in the PA-24-400 fuel system which will in some cases make engine starting difficult.

A valve has been developed to provide a positive means of purging the fuel system of this vapor. This valve complete with installation instructions is contained in Kit 756 922.

This kit should be ordered on the basis of one per airplane from the Service Spares Department at Lock Haven. Credit for the kit and six (6) hours of labor will be allowed when a Warranty and Credit Claim is received.

PIPER AIRCRAFT CORPORATION, LOCK HAVEN, PA., U. S. A.