

# SERVICE



# LETTER

Service Letter No. 325

December 24, 1959

**TO: All Distributors, Dealers, Owners and Operators**

**SUBJECT: Front Cabin Window Defroster Kit**

**MODELS AFFECTED: PA-24-180 and PA-24-250, Serial Numbers 24-1 to 24-1688 Inclusive**

We are pleased to announce the availability of a modification to eliminate the front cabin window frosting when operating the above listed airplanes in cold climatic conditions.

This modification employs the use of the thermopane principal and is available for field installation in kit form. The part number of this defroster modification kit is 754 293 and each kit will include two windows, one for the door and one for the left front window, and necessary parts for their installation. These two additional windows are installed on the inside of the present windows by means of clips.

This window defroster kit is available free of charge through your nearest Piper distributor or dealer. No warranty labor allowed.

Very truly yours,

PIPER AIRCRAFT CORPORATION

A handwritten signature in cursive script that reads "Robert Martin".

Robert Martin

Service Spares Manager

RM:mm

**PIPER AIRCRAFT CORPORATION, LOCK HAVEN, PA., U. S. A.**